Test stand attachment for peel tests SAUTER TPE-N





SAUTER

Universal attachment for test benches for 90 degree peel tests

Features

- The attachment for peel tests, SAUTER TPE-N has been specially developed for peel testing up to 500 N. Typically this involves pulling a bonded material layer from a base material. As a general rule the significant value in this process is the force required to pull away the top layer from bonded material
- The attachment can be fitted onto all SAUTER force measuring test benches quickly and easily and thereby offers the highest level of flexibility in terms of travel path, measuring range, sample fixing ecc.
- The attachment has been designed so that a bonded material, e.g. adhesive tape, plasters, etc, or an appropriate basic medium can be applied to the moving carriage. The test item is fixed to the force measuring device with a suitable clamp (both not included in the scope of delivery). Then the carriage is aligned such that the start of the test item is vertically immediately below the force measuring device. By moving the test bench upwards, the carriage is moved and the test item is peeled off at a 90-degree angle to the surface

- Suitable for all SAUTER force measuring devices up to 500 N (not included)
- Suitable for SAUTER test stands TVO 1000N500S, TVO 2000N500S, TVM 5000N230N, TVM 5000N230NL, TVS 5000N240, TVM 10KN120N, TVS 10KN100, (not included)

Technical data

- Maximum stripping length: 200 mm
- Overall dimensions W×D×H 425×100×60 mm
- Net weight approx. 4 kg

STANDARD

1 DAY

Model	Measuring range	
SALITER	[Max]	
OADTER	IN	
TPF-N	500	

SAUTER CATALOGUE 2022

Pictograms



Adjusting program (CAL): For quick setting of the instrument's accuracy. External adjusting weight required



Calibration block:

Standard for adjusting or correcting the measuring device



Peak hold function: Capturing a peak value within a

measuring process



Scan mode: Continuous capture and display of measurements



The measuring device can capture tension and compression forces



Length measurement: Captures the geometric dimensions of a test



Increases the measuring accuracy of a device within a defined measuring range



FOCUS

Internal memory:

To save measurements in the device memory



Data interface RS-232:

Bidirectional, for connection of printer and PC



Profibus:

For transmitting data, e.g. between scales, measuring cells, controllers and peripheral devices over long distances. Suitable for safe, fast, fault-tolerant data transmission. Less susceptible to magnetic interference.



Profinet:

Enables efficient data exchange between decentralised peripheral devices (balances, measuring cells, measuring instruments etc.) and a control unit (controller). Especially advantageous when exchanging complex measured values, device, diagnostic and process information. Savings potential through shorter commissioning times and device integration possible



Data interface USB:

To connect the measuring instrument to a printer, PC or other peripheral devices



Bluetooth* data interface:

Your KERN specialist dealer:

To transfer data from the balance/measuring instrument to a printer, PC or other peripherals



WLAN data interface:

To transfer data from the balance/measuring instrument to a printer, PC or other peripherals

Data interface Infrared: • (((() •





Control outputs (optocoupler, digital I/O): To connect relays, signal lamps, valves, etc.



To connect a suitable peripheral device for ANALOG analogue processing of the measurements

Analog output:



Statistics:

Im Using the saved values, the device calculates STATISTIC statistical data, such as average value, standard deviation etc.



PC Software: To transfer the measurement data from the device to a PC



A printer can be connected to the device to print out the measurement data

Network interface:



For connecting the scale/measuring instrument to an Ethernet network



KERN Communication Protocol (KCP):

It is a standardized interface command set for KERN balances and other instruments, which allows retrieving and controlling all relevant parameters and functions of the device. KERN devices featuring KCP are thus easily integrated with computers, industrial controllers and other digital systems

GLP/ISO record keeping: GLP

Of measurement data with date, time and PRINTER serial number. Only with SAUTER printers

Measuring units:

 ${\mathcal C}$ Weighing units can be switched to e.g. non-metric. UNIT Please refer to website for more details



Measuring with tolerance range (limit-setting function):

Upper and lower limiting can be programmed individually. The process is supported by an audible or visual signal, see the relevant model

*The Bluetooth® word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. and any use of such marks by KERN & SOHN GmbH is under license. Other trademarks and trade names are those of their respective owners.



ZERO:



Rechargeable set

Resets the display to "0"

<u> </u>
230 V

666

IP

+04

ZERO

Plug-in power supply:

230V/50Hz in standard version for EU. On request GB, AUS or USA version available

SAUTER

Protection against dust and water splashes IPxx:

The type of protection is shown in the

pictogram cf. DIN EN 60529:2000-09, IEC 60529:1989+A1:1999+A2:2013



Integrated power supply unit:

Integrated, 230V/50Hz in EU. More standards e.g. GB, AUS or USA on request



The mechanical movement is carried ELECTRO out by a electric motor

Motorised drive:

The mechanical movement is carried out by a synchronous motor (stepper)



STEPPER

Fast-Move:

The total length of travel can be covered by a single lever movement



Verification possible:

The time required for verification is specified in the pictogram

DAkkS +3 DAYS

DAkkS calibration possible: The time required for DAkkS calibration is shown in days in the pictogram



Factory calibration:



Package shipment: The time required for internal shipping preparations is shown in days in the pictogram

Pallet shipment:



The time required for internal shipping preparations is shown in days in the pictogram

+4 DAYS specified in the pictogram

The time required for factory calibration is